


# CM1 Thermal Cycle



- **CM1 Warmup**
  - 1/4/12 (Wed.) to 1/6/12 (Fri.) (~50 hours)
  - Verified turbo interlock system works
- **CM1 Cooldown**
  - Began 1/9/12 (Monday)
  - At 15:16 on 1/10/12 a vacuum burst occurred while Nitrogen Shields were at ~ 120K and the insulating vacuum suddenly declined from 1E-6 to 3 Torr.
  - Safety interlock system closed gate valves, protecting turbo pumps and RGA.

# Plot of Vacuum Event



# Diagnosis of Problem

- **Investigation**

- 1/10 evening shift and 1/11 day shift conducted studies that determined it was a leak from Nitrogen circuit to insulating vacuum
  - Installed roughing pumps on insulating vac. and connect RGA via bypass line to insulating vacuum space.
  - Used RGA and vacuum gauges to test each of the circuits (2 He. And 1 Nitrogen)


- **Results**

- Both Helium circuits showed no response (Good)
- Nitrogen circuit showed a direct vacuum and RGA response
- Vacuum was worse at upstream end of CM1

# Pressurizing Nitrogen



Fermilab



# Detailed Investigation


- **Next Step**

- Since leak was big enough that there was no hope of recovering insulating vacuum and/or cooling down 80K shields, decision was made to warm up, locate leak, and repair.


- **Pinpoint Leak**

- Cryo (Jerry Makara), TEV (Scott McCormick), and NML vacuum (Ron Kellett) experts led leak checking and repair efforts.
  - At Room temp., first verified warm leak, then connected (3) leak detectors (upstream, downstream, and on feedbox) tied into TEV chart recording cart, to give real-time comparison of response by each detector.
  - Flowed trace amount of helium into Nitrogen circuit from upstream feedbox and monitored response on leak detectors.

# Leak Check of CM1



# Plot of He Leak Check



- The leak detector test with helium showed the feed cap interface (green) responding first, followed by the feed can (red), and the end cap (blue). The delay is ~10 sec.

# Additional Leak Checks



- **Leak detector positions were swapped and test was repeated**
  - To verify the results were not equipment dependent (slower response time, etc.)
  - Results were consistent with first test
- **Additional tests were done to try to pinpoint if leak was in supply or return line**
  - Introduced He from downstream end, with supply line pressurized with Nitrogen and return line venting (to force He to only go through return-line path)
  - Introduced He into downstream end, with Nitrogen supply off (to repeat initial test, but with He coming from other end)


# Repair

- **Leak check and vacuum readings were all consistent and point towards leak at upstream interconnect region, supply side (possibly weld, bellows, or feedthru?)**
- **Repair Plan**
  - **Isolate all gas sources ✓**
  - **Vent CM1 insulating vacuum ✓**
  - **Open upstream bellows ✓**
  - **Remove insulation and shields to expose Nitrogen interconnects ✓**
  - **Inspect and leak check as necessary to find leak ✓**
  - **Repair leak ✓**
  - **Certify repair ✓**
  - **Close up and cooldown ✓**

# Repair – Update (1/27/12)


- **Large bellows on upstream end was opened and insulation and shields were removed.**
  - Initial visual inspection did not show any obvious problem.
  - Leak check of Nitrogen circuit by pressurizing with Nitrogen and using “Snoop” showed a leak at the supply side temperature sensor feedthrough.
- **Upstream Supply and Return temp. probes were removed and flanges blanked. New surface mounted sensors were installed at each location.**
- **Helium leak check was conducted to verify there were no leaks in Nitrogen circuit, and feedthru flanges were thermal shocked using liquid Nitrogen to verify they are leak tight.**

# Repair – Update (1/27/12)



Leak indicated by bubbling "Snoop"

Upstream LN2 Supply Line



Blanked Feedthru

Surface Mounted Sensor

# Repair – Update (2/1/12)

- **Surface mounted sensors were tested.**
- **Copper shields and superinsulation were installed on upstream end. Large bellows was closed and secured.**
- **Pump down of insulating vacuum and leak check was conducted. Nitrogen line and insulating vacuum space leak tight.**
- **Turbo pumps turned on.**
- **Cooldown started.**

# Timetable

- **1/4 – 1/6: Warmup (~ 50 hours)**
- **1/7 – 1/8: Weekend**
- **1/9: Began Cooldown**
- **1/10: Vacuum burst at 15:16, spent night shift troubleshooting**
- **1/11: Troubleshooting during day shift (using RGA and vacuum levels), determined it was a Nitrogen leak, decision to warm up, began warm-up in evening**
- **1/12: warm-up continued**
- **1/13: warm-up continued, installed 3 leak detectors**
- **1/14 – 1/16: Holiday weekend**
- **1/17: warm-up complete, leak checked, determined problem at upstream interconnect**
- **1/18-1/19: leak check continued, problem suspected at upstream supply interconnect**

# Timetable

- **1/20: Isolated gas supplies, vented insulating vacuum**
- **1/21-1/22: Weekend**
- **1/23: Upstream bellows opened, shielding & insulation removed, visual inspection**
- **1/24: “Snoop” leak check found leak in upstream supply temp. feedthru, Nitrogen supply isolated**
- **1/25: Removed supply and return side temp. probes and blanked-off feedthrus. He leak check of Nitrogen circuit to verify no leaks.**
- **1/26: Repeated leak check and thermal shocked blanked feedthrus with liquid Nitrogen.**
- **1/27: Completed installation of surface mounted sensors**
- **1/28-1/29: Weekend**
- **1/30: Tested temp. sensors, installed shield and insulation, closed large bellows, turned on pumps and did initial leak check**

# Timetable

- **1/31: Turbo pumps turned on, final leak checks conducted. Ready for cooldown**
- **2/1-2/3: Cooldown**
- **2/4-2/5: Weekend**
- **2/6: Cooldown completed**