


Tevatron (150 GeV and flattop) proton horizontal emittance

Nov. 1, 2008 – Feb. 2, 2009



Checking if the emittances (especially at flattop) were decreased after multibatch operation

Is the step down (after the fix) a problem?

Tevatron (150 GeV and flattop) proton vertical emittance

Nov. 1, 2008 – Feb. 2, 2009

