

Synclite Status


Pbar mirror is inserted every store

Camera focus adjusted


Object / image distances tweaked

Instrumentation effects accounted for


Synclite Status




Synclite Status




Synclite Status



Synclite Status



Synclite Status



Synclite Status

- Would like to do EOS dispersion measurement at 980