


Appendix J:

Photographs of Pipe Interior (S530-01) (Internal Video Prints)



— BOTTOM OF PIPE, AFTER REPAIR
— BEFORE CLEANING (3530-01)



— TOP OF PIPE, AFTER REPAIR
— BEFORE CLEANING (5530-01)