





Booster Prototype Replacement Cavity Update

3/14/19

Slabaugh



Drill template



Alignment fixturing

Alignment fixturing





Ceramic welding

- Welding performed 3/8/19
- Leak check completed 3/11/19
- Final welds planned 3/15/19

- 
- # Ceramic welding
- Welding performed 3/8/19
 - Leak check completed 3/11/19
 - Final welds planned 3/15/19

Gradient ring installation

